



Spencer Mine



P1: Spencer Mine headframe collapsed into shaft due to arroyo capture and undercutting



P2: Spencer Mine vent shaft



P3: Spencer Mine building pad



P4: Spencer Mine Waste pile cut through by arroyo





P5: Spencer Mine waste pile cut by drainage